SWISS DESIGN

Automatic Blood Pressure Monitor

Model: X3

Bluetooth®
Data Transmission

- Bluetooth® low energy Technology
- Cuff Detection
- Movement Detection
- Hypertension Risk Indication
- Irregular Heartbeat Detection (IHB)
- Average of Last 3 Readings
- 120 Memories for 2-users With Date and Time Indication
- Guest Mode
- One-Touch Automatic Operation
- Cuff Holder Design
- Large LCD size : 57*73 mm
- Adaptor Socket
- Lifetime Calibration
- PC Link (optional)
- String Bag
- Latex-Free Patented Universal Cone Cuff

Universal Cone Cuff 24~40cm

CONE CUFF Patented

Latex free

CE

Bluetooth® low energy Technology

Cuff Detection

Movement Detection

Hypertension Risk Indication

Irregular Heartbeat Detection (IHB)

Average of Last 3 Readings

120 Memories for 2-Users With Date and Time Indication

Guest Mode

Cuff Holder Design

Jumbo Size "XL" Digit

Dual Power Ready

String Bag

5 YEAR WARRANTY LIFETIME CALIBRATION

ESH European Society of Hypertension protocol

BIHS British & Irish Hypertension Society listed

Cuff Detection (CD)

OK

Detects and indicates whether the cuff is wrapped around the arm properly

Movement Detection

The "Movement Detection" helps reminding the user to remain still and is indicating any body movement during measurement. The specified icon appears once a "body movement" has been detected during and after each measurement.

Universal Cone Cuff 24~40cm

Universal Cone cuff fits arm circumference: 24~40cm (9.4"~15.7") Other size cuffs available upon request

Model	Qty per carton	Carton volume
X3	18 pcs	0.051 cbm/ctn

QTY per 20'	QTY per 40'	QTY per 40'HQ
9882 pcs	19764 pcs	22932 pcs

Storage and Transportation Condition
-10°C~60°C(14°F~140°F)
10%~90% RH, 700~1060 hPa

Real ƒuzzy Technology

Real Fuzzy Technology determines ideal cuff pressure based on one's systolic blood pressure and arm size. Users no longer need to pre-set the inflation level before measurement. The technology eliminates arm discomfort through unnecessary high inflation settings and also prevents inaccurate readings caused by erroneous cuff inflation levels.